

## **REPORT NUMBER:**

# HGHT08187216





## TEST REPORT

Number : HGHT08187216

Date : Nov 08, 2024

Applicant : HANGZHOU ZHONGZHI INDUSTRY CO.,LTD 20TH FLOOR, BUILDING 4, BUILDING 4, NO. 332 QIUTAO NORTH ROAD, SHANGCHENG DISTRICT, HANGZHOU CITY, ZHEJIANG PROVINCE, CHINA

Attn: WAN WAN

Sample Description As Declared :		
No. Of Sample	:	One (1)
Fibre Content	:	-
Material	:	Knitted Socks
Finishing	:	-
End Uses	:	Men/Women Socks
Colour	:	Mix
Style No.	:	-
Order No./PO No.	:	-
Buyer's Name	:	-
Manufacturer's Name	:	HANGZHOU ZHONGZHI INDUSTRY CO., LTD
Ref.	:	-
Applicant's Provided Care Instruction/Label:		
-		
Date Sample Received	:	Nov 05, 2024
Date Testing Started	:	Nov 05, 2024

Prepared And Checked By: For Intertek Testing Services Ltd., Hangzhou

Vivian Zhao Manager



Page 1 Of 2

Intertek Testing Services Ltd., Shanghai,Hangzhou Branch 2F, 3F, 4F, 6F's Room 601-618, Building 6, No. 1180, Bin'an Road, Changhe Street, Binjiang District, Hangzhou, Zhejiang, China 上海天祥质量技术服务有限公司杭州分公司 中国浙江省杭州市滨江区长河街道滨安路 1180 号 6 幢 2 层、3 层、4 层、6 层 601-618 室 邮编:310052 Tel: +86 571 8768 8218 Fax: +86 571 8679 0296 E-mail: hztmr@intertek.com Attention is drawn to the terms and conditions on Website: www.intertek.com.cn/responsibility



### TEST REPORT

Number : HGHT08187216

#### Tests Conducted (As Requested By The Applicant) 1 Bisphenol A Content:

By Solvent Extraction, Followed by Liquid Chromatography Tandem Mass Spectrometry (LC-MS-MS) Analysis.

Result (ppm) ND

Remark: ppm = parts per million = mg/kg Detection Limit = 0.1 ppm ND = Not Detected

End of Report

This report is made solely on the basis of your instructions and/or information and materials supplied by you. It is not intended to be a recommendation for any particular course of action. Intertek does not accept a duty of care or any other responsibility to any person other than the Client in respect of this report and only accepts liability to the Client insofar as is expressly contained in the terms and conditions governing Intertek's provision of services to you. Intertek makes no warranties or representations either express or implied with respect to this report save as provided for in those terms and conditions. We have aimed to conduct the Review on a diligent and careful basis and we do not accept any liability to you for any loss arising out of or in connection with this report, in contract, tort, by statute or otherwise, except in the event of our gross negligence or wilful misconduct.

This report shall not be reproduced except in full, without written approval of the laboratory.

Page 2 Of 2

Intertek Testing Services Ltd., Shanghai,Hangzhou Branch 2F, 3F, 4F, 6F's Room 601-618, Building 6, No. 1180, Bin'an Road, Changhe Street, Binjiang District, Hangzhou, Zhejiang, China 上海天祥质量技术服务有限公司杭州分公司 中国浙江省杭州市滨江区长河街道滨安路 1180 号 6 幢 2 层、3 层、4 层、6 层 601-618 室 邮编:310052 Tel: +86 571 8768 8218 Fax: +86 571 8679 0296 E-mail: hztmr@intertek.com Attention is drawn to the terms and conditions on Website: www.intertek.com.cn/responsibility